



Photo 1 – Power lines that were struck by N64702.



Photo 2 - Burnt wreckage of N64702 (foreground) and power lines that were struck (background).



Photo 3 - Frontal view. Power lines are to the left.



Photo 4 - The wreckage of N64702.