



Photo 1 – Damaged airplane Photo courtesy of FAA



Photo 2 - Broken tailwheel link Photo courtesy of FAA