




Photo 1 – View of Number 4 Cylinder




Photo 2 – View of Number 4 Cylinder



Photo 3 – View of Number 4 Cylinder Crack