



Photo 1 – The fuel pump installed on N302CT's engine



Photo 2 – The fuel pump diaphragm before removal from engine



Photo 3 – Hole in fuel pump diaphragm



Photo 4 – Side view of hole in fuel pump diaphragm