




Photo 1 – Google Earth with flight track




Photo 2 – Google Earth end flight track




Photo 3 – Google Earth close up of accident area



Photo 4 – Vertical stabilizer and rudder



Photo 5 – Vertical stabilizer spar



Photo 6 – Box of airplane pieces