



Photo 1 – Main wreckage in a corn field



Photo 2 – Main wreckage front left



Photo 3 – Main wreckage rear



Photo 4 – Vertical stabilizer wire strike damage



Photo 5 - Rudder



Photo 6 – View of power lines from the main wreckage




Photo 7 – Google Earth flight path




Photo 8 – Google Earth flight path



Photo 9 – Google Earth flight path