



Photo 1 – Accident airplane as it came to rest in ditch.



Photo 2 – Tire markings on runway, leading into the grass off the runway surface to the location of the airplane.



Photo 3 - Close-up of damage to left wing.