



Copyright by Mark Pasqualino | 2009-07-31 | KOSH | Airport-Data.com

Photo 1 – Pre-accident photo of N76S.



Photo 2 – Pre-accident photo of N76S's instrument panel.



Photo 3 – N76S's instrument panel at the accident site.



Photo 4 – The wreckage of N76S.



Photo 5 – The empennage. Note left deflection of the rudder.



Photo 6 – Left side of fuselage. Note creases at instrument panel and pilot's seat. Top to bottom, left to right.



Photo 7 – Left engine and propeller.



Photo 8 – Right engine and propeller.