



Photo 1 – Main wreckage as viewed from left



Photo 2 – Main wreckage as viewed from rear



Photo 3 – Main wreckage as viewed from right rear



Photo 4 - View of airplane instrument panel



Photo 5 - View of engine



Photo 6 - View of impacted trees



Photo 7 – Left view of engine during examination



Photo 8 - Right view of engine during examination



Photo 9 – Aerial view of accident site



Photo 10 – Satellite view of runway and accident location