



Photo 1 – Accident Site Overview



Photo 2 - Accident Site Overview



Photo 3 - Accident Site Overview (Empennage)



Photo 4 - Accident Site Overview (Engine and Propeller)



Photo 5 - Right Gull-Wing Cabin Door Overview



Photo 6 - Right Gull-Wing Cabin Door Latch



Photo 7 - Forward Latch Pin



Photo 8 - Aft Latch Pin



Photo 9 - Right Gull-Wing Cabin Door (After Recovery)



Photo 10 - Forward Latch Pin (Fully Latched)



Photo 11 - Aft Latch Pin (Fully Latched)