



Photo 1 – Aerial photo of accident site (FAA)



Photo 2 – View of skid marks on the runway (FAA)



Photo 3 – View of wheel marks in the grass



Photo 4 – Wheel marks in the snow and on the taxiway (FAA)



Photo 5 – Wheel marks in the grass and snow near the accident site (FAA)



Photo 6 – View of Chevy Tahoe tipped on its side and the airplane wreckage (FAA)



Photo 7 – View of airplane wing 90 ft away from the main wreckage (FAA)



Photo 8 – View of the right side of the Chevy Tahoe (FAA)



Photo 9 – View of the baggage found in the wreckage (FAA)



Photo 10 – View of propeller blade with a gouge in the leading edge



Photo 11 – View of propeller blade with scuff mark on the chamber side of the blade



Photo 12 – View of propeller blade tip



Photo 13 – View of rudder cable and elevator control tube




Photo 14 – View of engine RPM and tach gauge



Photo 15 – View of windsock on the day of the accident (FAA)