



Photo 1 – Witness Photo of Airplane Above Departure End of Runway



Photo 2 – Witness Photo of Airplane in Right Bank Turn Near Departure End of the Runway



Photo 3 - Witness Photo of Airplane Climb with a Right Bank



Photo 4 - Witness Photo of Airplane at Higher Altitude with a Left Bank



Photo 5 - Witness Photo of Airplane at Higher Altitude with an Approximate 80 to 90-Degree Left Bank



Photo 6 – Last Witness Photo of Airplane with a Nose-Down Left Bank Before Impact with Terrain



Photo 7 – Last Witness Photo of Airplane with a Nose-Down Left Bank Before Impact with Terrain