



Photograph 01 - Airplane in the river (provided by LEO)



Photograph 02 - Forward Fuselage



Photograph 03 - Front view of wreckage



Photograph 04 -Left Wing



Photograph 05 - Empennage



Photograph 06 - Right wing



Photograph 07 - Front Seat



Photograph 08 - Rear Seat



Photograph 09 - Instrument Panel



Photograph 10 - Front lap belt, left side



Photograph 11 - Front lap belt, right side



Photograph 12 - Front seat, left side mounting hardware



Photograph 13 - Front shoulder harness



Photograph 14 - Rear lap belt, left side mounting wire bracket



Photograph 15 - Rear lap belt, right side



Photograph 16 - Rear shoulder harness



Photograph 17 - Front shoulder harness mount (Provided by FAA)