



Photo 1 – View of the airplane at the accident site.



Photo 2 - View of the airplane at the accident site.



Photo 3 - View of the airplane at the accident site.



Photo 4 - View of the airplane at the accident site.



Photo 5 - View of the baggage compartment door.



Photo 6 - View of separations in the push pull tubes.




Photo 7 - View of separations in the push pull tubes.




Photo 8 - View of the 5-gallon wing tank shut off valve.



Photo 9 - View of separations in the flight control cables.



Photo 10 - View of a limitations placard.



Photo 11 - View of the instrument panel.




Photo 12 - View of separations in a push pull tube.



Photo 13 - View of a propeller blade.



Photo 14 - View of the right side wings.



Photo 15 - View of recovered liquid from the fuel system.



Photo 16 - View of the ground scar under the wings.



Photo 17 - View of the ground scar under the engine.



Photo 18 - View of the fuel servo.



Photo 19 - View of the screen from the fuel servo.



Photo 20 - View of removed spark plugs.