



Photo 1 – Main Wreckage Overview



Photo 2 – Forward Fuselage and Cabin



Photo 3 – Right Wing



Photo 4 – Engine and Propeller



Photo 5 – Propeller




Photo 6 – Overview of Rudder Pedal Guard Device



Photo 7 - Overview of Rudder Pedal Guard Device



Photo 8 – Pilot's Dog Seated in Accident Airplane