



**Photo 1 – View of Oil Filter Metal Deposits**



**Photo 2 – View of Number 1 Piston and Failed Plug**



**Photo 3 – View of Failed Piston Pin Plug**



**Photo 4 – View of Number 4 Connecting Rod Bearing**



**Photo 5 – View of Number 1 Cylinder Bore**