



Photo 1 – B-100's tire tracks going off the runway



Photo 2 – View of the end of runway 18



Photo 3 – View of airplane's tire tracks at the ILS structure



Photo 4 – View of the damaged ILS structure damage



Photo 5 – View of the damaged ILS structure looking back at the runway



Photo 6 – View of left side of the airplane with the collapsed nose and left main landing gear



Photo 7 – View of the airplane from in front of the airplane



Photo 8 – View of the airplane from the left side of the airplane



Photo 9 – View of the airplane from the rear



Photo 10 – View of the right side of the airplane



Photo 11 – View of the left engine nacelle and propeller



Photo 12 – View of the right engine nacelle and propeller



Photo 13 – View of damage to the left wing



Photo 14 – View of damage to the left wingtip



Photo 15 – View of the baggage in the baggage compartment



Photo 16 - View of the baggage in the baggage compartment



Photo 17 – View of the pilot's instrument panel and flight controls



Photo 18 – View of the copilot’s instruments and flight controls