



Photo 1 – Accident Site (New Mexico DPS Photo)



Photo 2 – Accident Airplane



Photo 3 – Accident Airplane



Photo 4 – Accident Airplane



Photo 5 - Engine



Photo 6 - Engine



Photo 7 - Engine




Photo 8 - Engine




Photo 9 – Fuel Tee Fitting



Photo 10 - Cap



Photo 11 - Cap




Photo 12 – Fuel Tee Fitting and Cap