



Photo 1 – Airplane bottom cowling area

photo courtesy of FAA



Photo 2 - View of burnt drain line

photo courtesy of FAA



Photo 3 – Burnt fuel drain line

photo courtesy of FAA