



Photo 1 – View of the aircraft in the grass off the side of the runway



Photo 2 – View of the aircraft resting on the left wing



Photo 3 – View of the airplane from the left side of the aircraft



Photo 4 – View of the damaged left wing



Photo 5 – View of the damaged left wing and collapsed left main landing gear



Photo 6 – View of cockpit instrument panel