



Photo 1 – Supplied photo showing a front right quartering view of the airplane resting off the left side of runway 31.



Photo 2 - Supplied photo showing an aft right quartering view of the airplane resting off the left side of runway 31.



Photo 3 - Supplied photo showing an aft view of the airplane resting off the left side of runway 31. A displaced taxiway sign is present in the snow near the pilot's cabin door.



Photo 4 - Supplied photo showing a front view of the airplane resting off the left side of runway 31. A displaced taxiway sign is present in the snow near the pilot's cabin door.



Photo 5 - Supplied photo of a ground scar extending from the edge of the runway to the airplane's resting location.



Photo 6 - Supplied close-up photo of a ground scar extending from the edge of the runway to the airplane's resting location.



Photo 7 - Supplied close-up photo of a ground scar extending from the edge of the runway to the airplane's resting location.




Photo 8 - Supplied close-up photo of deformed structure near the lower fuselage.



Photo 9 - Supplied close-up photo of runway witness marks with the accident airplane in the background.



Photo 10 - Supplied photo of the separated nose landing gear.