



Photo 1 – N5VK near the edge of the plateau. Rescue helicopter is in background.



Photo 2 – Gascolator contained rust and debris.



Photo 3 – Fuel filter also contained rust and debris.



Photo 4 – Engine being functionally tested.



Photo 5 – Damaged propeller governor cable.