



Photo 1 – Damaged airplane

Photo courtesy of FAA



Photo 2 – Engine Oil Sump

Photo courtesy of FAA




Photo 3 – Vacuum pump

Photo courtesy of FAA