



Photo 1 – Wreckage and Path of Travel (FAA Photo)



Photo 2 – Port Side View of Wreckage (FAA Photo)



Photo 3 – Front View of Wreckage (FAA Photo)



APR 74

Photo 4 – North View of Runway (Insurance Photo)



Photo 5 – South View of Runway (Insurance Photo)



Photo 6 – Propeller Blade (Insurance Photo)



LP 1841W

Photo 7 – Left Main Tire (Insurance Photo)



LP 27

Photo 8 – Left Main Tire (Insurance Photo)



RT Main

Photo 9 – Right Main Tire (Insurance Photo)