



Photo 1 – View from the front of the airplane wreckage



Photo 2 – Left side of the airplane with the left wing and left elevator missing



Photo 3 – View of the wreckage from the right side of the wreckage



Photo 4 – View of the fragmented left wing in the trees



Photo 5 – View of left wing in the trees



Photo 6 – View of left wing fuel tank in front of the airplane wreckage



Photo 7 – View of the left fuel tank filler neck



Photo 8 – View of the right fuel tank in the wreckage



Photo 9 – View of right wing fuel tank amidst the fragmented right wing wreckage



Photo 10 – View of fuel selector pointing to the OFF position



Photo 11 – View of engine on test stand



Photo 12 – View of engine operating on the engine run stand