



Photo 1 – Balloon Gondola



Photo 2 – Gondola Damage




Photo 3 – Suspension Cables Damage



Photo 4 – Second Suspension Cables Damage




Photo 5 – Second Suspension Cables Damage, Detail



Photo 6 - Burners



Photo 7 – Balloon Envelope