



Photo 1 – Airplane at Accident Site



Photo 2 – Accident Site Landing Gear Tracks Leading to Airplane



Photo 3 – Cracked Cylinder



Photo 4 – Closeup of Cracked Cylinder