



Photo 1 – Airplane Wreckage at Accident Site




Photo 2 – Throttle Cable Mounting Block Separated




Photo 3 – Throttle Cable Mounting Block Re-Positioned in Original Location