



Photo 1 – View of hose routing on N9306 (accident airplane)




Photo 2 – View of hose routing on exemplar airplane at Mooney factory