



Photograph 1 – Main Wreckage and Ground Scar (Provided by the FAA)



Photograph 2 – The Engine and Propeller Assembly (Provided by the FAA)



Photograph 3 – Fuel Tank Foam Baffle



Photograph 4 – Fuel Flow Divider (Provided by Lycoming)