



Photo 1 – View of the wreckage in a bean field.



Photo 2 – View of initial impact point and the main wreckage



Photo 3 – View of the left wing and fuselage of the airplane



Photo 4 – View of wreckage from the rear of the airplane with the tree line in the background



Photo 5 – View of the right wing



Photo 6 – View of right outboard wing



Photo 7 – View of section of right wing leading edge found in the tree line and mated right wing surface



Photo 8 – View of right wingtip navigation light found in tree line



Photo 9 – View of propeller blades at the accident site



Photo 10 – View of propeller blade with blade twist and burnishing



Photo 11 – View of propeller blade with blade twist at the tip



Photo 12 - View of propeller blade with blade twist