



Photo 1 – Airplane at Accident Site



Photo 2 – Main Landing Gear at Accident Site



Photo 3 – Front of Airplane and Main Landing Gear



Photo 4 – Hydrasorb Shock Units



Photo 5 – Left Main Landing Gear Brace Tube



Photo 6 – Left Hydrasorb Shock Unit



Photo 7 – Right Hydrasorb Shock Unit