



Photo 1 – Inverted NC68N in the cornfield after its forced landing. Note vegetation wrapped around engine cowling.



Photo 2 – Inverted Golden Eagle Chief, with swath in background.



Photo 3 – Crushed vertical stabilizer.