




Photograph 01 - Initial impact point, ground scars, and right wing



Photograph 02 - Front view of the airplane



Photograph 03 - Instrument panel