



Photo 1 – Accident Airplane After Ground Loop



Photo 2 – Accident Site – Photo Taken by J.P. Slimmer



Photo 3 – Initial Impact



Photo 4 - Wreckage



Photo 5 - Wreckage



Photo 6 – Wreckage



Photo 7 – Right Wing



Photo 8 – Fuel Tanks



Photo 9 - Empennage



Photo 10 - Empennage



Photo 11 – Flight Controls



Photo 12 – Flight Controls



Photo 13 - Propeller



Photo 14 – Engine from N428AP