

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety (AS-30)

Air Traffic Investigations

NTSB Investigation Number

CEN18FA009

Figure 3 - N8338S Flight Track

Overview with times and altitudes

B. SOPER

OCTOBER, 2019

1936:37 MDT / 6,850 msl

1940:49 MDT / 8,000 msl

1944:13 MDT / 8,000 msl

1946:13 MDT / 8,000 msl

1948:49 MDT / 7,650 msl

1951:25 MDT / 7,825 msl

1955:39 MDT / 7,925 msl

1958:40 MDT / 7,650 msl

2002:17 MDT / 7,650 msl

Last recorded track data 775 ft west of accident site 2002:17 MDT / 7,650 msl

6/18/2018 8:25:06 pm

Prepared by

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety (AS-30)

Air Traffic Investigations

NTSB Investigation Number

CEN18FA009

Figure 1 - N8338S Flight Track

Overview

B. SOPER

OCTOBER, 2019




Image Landsat / Copernicus
© 2018 Google
© 2018 INEGI

Google Earth

6/18/2018 8:25:06 pm

Prepared by

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety (AS-30)

Air Traffic Investigations

NTSB Investigation Number

CEN18FA009

Figure 2 - N8338S Flight Track

Final Segment

B. SOPER

OCTOBER, 2019

ACCIDENT SITE

Google Earth

© 2018 Google
© 2018 INEGI