



Photo 1 – View of the airplane wreckage from the aft ride side



Photo 2 - View of the airplane wreckage from the ride side



Photo 3 – View of the airplane wreckage from the left side



Photo 4 – View on ground impact marks on the left side of the airplane



Photo 5 – A view of the left side the airplane with ground scars visible



Photo 6 – A piece of the red navigation lens



Photo 7 – View of the wreckage from aft of the empennage



Photo 8 – View of the metal right wing fuel tank



Photo 9 - Photo 9 – View of the metal left wing fuel tank



Photo 10 – View of the engine



Photo 11 – View of the engine hanging by a chain



Photo 12 – View of the propeller still attached to the wreckage



Photo 13 – A view of the propeller separated from the engine



Photo 14 – A view of one of the propeller blades with blade twist and bending



Photo 15 – View of 4 spark plugs from the top of the cylinders