

CEN18FA037
Cessna 172G, N4676L
Pittsford, Vermont
November 22, 2017

Plotted GPS Data




Figure 1 - Plotted GPS data of accident flight showing elevation profile.




Figure 2 - GPS plot showing the airplane flight path following US Highway 7.




Figure 3 - GPS Plot showing the flight path diverging from the road where the road turns left.




Figure 4 - GPS Plot of airplane within a valley before making a left turn and crossing one of the ridges forming the valley.




Figure 5 - Final portion of GPS data showing the descending right hand turn before the end of the recorded data.