



Photo 1 – Accident airplane airborne, a white trail (smoke) Photo taken from security video: courtesy of LPD



Photo 2 - The white trail appeared to stop as the airplane turns. Photo from security video: courtesy of LPD



Photo 3 – The airplane in a left steep bank. Photo taken from security video: courtesy of LPD



Photo 4 - The airplane in a steep bank, just above the ground. Photo taken from security video: courtesy of LPD



Photo 5 – Accident airplane just before impact with terrain. Photo from security video: courtesy of LPD



Photo 6 - White trail of smoke behind accident airplane. Witness photo, courtesy of FAA



**Photo 7 – Close-up view of the airplane; area under the left engine is dark. The landing gear is down.
Witness photo, courtesy of FAA**