



Photo 1 – Ground Scarring with Main Wreckage



Photo 2 – Left Side of Main Wreckage



Photo 3 – Airspeed Indicator




Photo 4: Left Side Pilot Seat Frame