



Photo 1 – Accident Site




Photo 2 – Main Wreckage, Front View



Photo 3 – Main Wreckage, Left Side View



Photo 4 – Main Wreckage, Aft View



Photo 5 – Main Wreckage, Right Side View



Photo 6 – Electric Motor and inboard 2/3rds of one of two Propeller Blades



Photo 7 – Propeller Blade Tip



Photo 8 – Propeller Blade Two



Photo 9 – Initial Impact Ground Scar