



Photo 1 – Accident Site



Photo 2 – Accident Site



Photo 3 – Inverted Airplane Left Side



Photo 4 – Engine and Propeller



Photo 5 – Engine Compartment Cob Webs




Photo 6 – Engine and Spark Plugs



Photo 7 – Empty Beer Can



Photo 8 – Gascolator and Hydraulic Line



Photo 9 – Engine Oil Filter



Photo 10 – EverStart Automotive Battery



Photo 11 – Mud Dauber Nest In Oil Cooler



Photo 12 – Fuel Drained From Left Wing Tank



Photo 13 – Rodents Nest In Left Wing



Photo 14 – Wire On Front Left Seat



Photo 15 – Automotive Hydraulic Hose Used As Main Fuel Line



Photo 16 – Organic Debris In Fuel Line Fitting



Photo 17 - Organic Debris In Fuel Fitting