


Prepared by
NATIONAL TRANSPORTATION SAFETY BOARD
 Office of Aviation Safety (AS-30)
 Air Traffic Investigations

NTSB Investigation Number
CEN18FA371

Figure 1 - C-GLKX Flight Track
Flight Overview

B. SOPER

JULY, 2019



Prepared by

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety (AS-30)
Air Traffic Investigations

NTSB Investigation Number
CEN18FA371

Figure 2 - C-GLKX Flight Track
RNAV RWY 22 at KPHN

B. SOPER

JULY, 2019



Google Earth

Prepared by

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety (AS-30)
Air Traffic Investigations

NTSB Investigation Number
CEN18FA371

Figure 3 - C-GLKX Flight Track
RNAV RWY 22 at KPHN

B. SOPER

JULY, 2019



ACCIDENT SITE

Image Landsat / Copernicus

Image NOAA

Google Earth

Prepared by

NATIONAL TRANSPORTATION SAFETY BOARDOffice of Aviation Safety (AS-30)
Air Traffic InvestigationsNTSB Investigation Number
CEN18FA371**Figure 4 - C-GLKX Flight Track**
Final Segment / Times and Key Points

B. SOPER

JULY, 2019

