



Photo 1 – View of the airplane wreckage from the front left of the airplane



Photo 2 – View from the right front of the wreckage



Photo 3 – View of the wreckage from the right rear



Photo 4 – View of the wreckage from the right side of the airplane



Photo 5 – View of the wreckage from the left side of the airplane



Photo 6 – View of the right wingtip tank



Photo 7 – View of the top of the right nacelle fuel tank and cargo locker (Textron photo)



Photo 8 – View of the right wing and right auxiliary fuel tank (Textron photo)



Photo 9 – View of the right engine



Photo 10 – View of the right propeller stuck in the ground at its initial impact point



Photo 11 – The right propeller after it was removed from the impact crater



Photo 12 – View of the right wing that had fire damage



Photo 13 – View of fire damage to the left wing



Photo 14 – View of left propeller initial impact point and airplane wreckage



Photo 15 – View of left engine and left propeller



Photo 16 – Left wing fuel valve (Textron Photo)



Photo 17 – Right wing fuel valve (Textron photo)



Photo 18 – Cockpit right engine fuel selector valve (Textron photo)



Photo 19 – Engine Tach RPM gauge for both engines (Textron photo)



ST CLAIR COUNTY SHERIFF'S OFFICE

INVESTIGATOR:	DET. RICKERT	LOCATION:	ST. CLAIR TOWNSHIP	COUNTY:	ST CLAIR
		DATE DRAWN:	09/15/2018		
DRAWN BY:	DEP R NOWISKI			SCALE:	1" = 20FT

Photo 20 – Overhead drone photo and map (St Clair Sheriff's Office)