




Photo 1 – Puntilla Lake weather camera directions




Photo 2 – Puntilla Lake southeast camera, clear day photo

Mon 24 Sep 2018 18:17:07 UTC
Mon 24 Sep 2018 10:17:07 AKDT

Puntilla Lake - SouthEast
See <https://avcams.faa.gov> for more information



Photo 3 - Puntilla Lake southeast camera, accident day

Mon 24 Sep 2018 18:27:06 UTC
Mon 24 Sep 2018 10:27:06 AKDT

Puntilla Lake - SouthEast
See <https://avcams.faa.gov> for more information



FAA advisory weather product

Photo 4 - Puntilla Lake southeast camera, accident day




Photo 5 - Puntilla Lake north camera, clear day photo

Mon 24 Sep 2018 18:17:07 UTC
Mon 24 Sep 2018 10:17:07 AKDT

Puntilla Lake - North
See <https://avcams.faa.gov> for more information



Photo 6 - Puntilla Lake north camera, accident day

Mon 24 Sep 2018 18:27:07 UTC
Mon 24 Sep 2018 10:27:07 AKDT

Puntilla Lake - North
See <https://avcams.faa.gov> for more information



Photo 7 - Puntilla Lake north camera, accident day




Photo 8 - Puntilla Lake northwest camera, clear day photo

Mon 24 Sep 2018 18:12:11 UTC
Mon 24 Sep 2018 10:12:11 AKDT

Puntilla Lake - NorthWest
See <https://avcams.faa.gov> for more information



FAA advisory weather product

Photo 9 - Puntilla Lake northwest camera, accident day

Mon 24 Sep 2018 18:22:11 UTC
Mon 24 Sep 2018 10:22:11 AKDT

Puntilla Lake - NorthWest
See <https://avcams.faa.gov> for more information



Photo 10 - Puntilla Lake northwest camera, accident day