

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Oscoda Wurtsmith Airport State: MI
 ZIP: 48750 Country: Iosco
 Latitude: N44.416 Longitude: W 137.83485772
(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 09/25/2018 Local Time: 0613
mm/dd/yyyy Time Zone: EDT

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N241CK

Manufacturer: Beech Craft

Model: B-200

Serial Number: BB272

Year of Manufacture: 1977

Amateur-Built: ☐ Yes ☐ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

☒ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 12,500 lbs

Weight at Time of Accident/Incident: _____ lbs

Number of Seats: 9 Flight Crew Seats: 2

Cabin Crew Seats: 0 Passenger Seats: 7

Number of Engines: 2

Category of Aircraft

- ☒ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☐ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
- ☐ Aerobatic
- ☐ Balloon
- ☐ Commuter
- ☐ Transport
- ☐ Utility
- ☐ Restricted
- ☐ Limited
- ☐ Provisional
- ☐ Special Flight
- ☐ Experimental
- ☐ Special Light-Sport
- ☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

- ☐ Retractable
- ☒ Tricycle
- ☐ Amphibian
- ☐ Emergency Float
- ☐ Float
- ☐ Hull
- ☐ Other Launch/Recovery System
- ☐ None
- ☐ Tailwheel
- ☐ High Skid
- ☐ Skid
- ☐ Ski
- ☐ Ski/Wheel
- ☐ Unknown

Engine Type *(Select one)*

- ☐ Reciprocating
- ☐ Turbo Shaft
- ☒ Turbo Prop
- ☐ Turbo Jet
- ☐ Turbo Fan
- ☐ Electric
- ☐ Liquid Rocket
- ☐ Solid Rocket
- ☐ Hybrid Rocket
- ☐ None
- ☐ Unknown

Fuel System Type *(Reciprocating)*

- ☐ Carburetor
- ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. <i>mm dd yyyy</i>	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Pratt and Whitney	PT 6A-41	PCE80581	07/11/1977	850	13912.7	89.2	7742.2
Eng. 2	Pratt and Whitney	PT6A-41	PCE80282		850	12802.5	89.2	6747.3
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour
- ☒ AAIP
- ☐ Annual
- ☐ Continuous Airworthiness
- ☐ Conditional Inspection
- ☐ Unknown

Date Last Inspection: 03/28/2018
mm/dd/yyyy

Airframe Total Time: 13933.6 hrs
 hours measured at *(Select one)*
☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program *(Select one)*

- ☐ Annual
- ☐ Conditional (Amateur-built only)
- ☐ Manufacturer's Inspection Program
- ☒ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
- ☒ Specify: AK Manufacture system Hand held

Propeller 1

- ☐ Fixed Pitch
- ☒ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: Hartzell
 Model: HC-B3TN-3G

Propeller 2

- ☐ Fixed Pitch
- ☒ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: Hartzell
 Model: HC-B3TN-3G

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: Narco

Model or Part No.: ELT-10

TSO No.: ☐ C91 (121.5 MHz) ☒ C91a (121.5 MHz)
☐ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☒ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft: ☒ Yes ☐ No

If not activated:

- Indicate Reason:
- ☐ Impact Damage
 - ☐ Fire Damage
 - ☐ Battery Expired/Damaged
 - ☐ Unknown

Additional Equipment *(Check all that apply)*

- ☐ ADS-B
- ☐ Airframe Parachute
- ☐ Angle of Attack Indicator
- ☒ Autopilot
- ☐ Data Recorder
- ☒ Electronic Flight Bag or Handheld Device
- ☒ Electronic Multifunction Display
- ☐ Electronic Primary Flight Display
- ☐ Handheld GPS
- ☐ Heads Up Display
- ☐ Onboard Weather
- ☐ Satellite Tracking Device
- ☐ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Kalitta Equipment LLCFractional Ownership Aircraft: ☐ Yes ☒ NoCity: YpsantiState: MIZIP: 48198Country: USA**Operator of Aircraft**☐ Same As Registered Owner☐ Same Address as Registered OwnerName: Kalitta Charters LLCCity: [REDACTED]

Doing Business As: _____

State: MIZIP: 48198Air Carrier/Operator Designator (4 Character Code): KC8ACountry: USA**Operating Certificates Held**

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☒ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437

- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial

- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International

☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☒ Business ☐ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)Airport Name: Oscoda Wurtsmith AirportAirport Identifier: KOSCProximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/ADistance From Airport Center: 5.8 smDirection From Airport: 060 degrees trueAirport Elevation: 633 ft. msl**Runway Information**Runway ID: 06 (L/R/C) Length: 11,800 ft Width: 200 ft**Runway/Landing Surface** (Check all that apply)

- ☐ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☒ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☐ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☒ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Final ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☒ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☒ None
☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION**"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident**

☒ Pilot ☐ Co-Pilot ☐ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: David

City of Residence: Davenport

Middle Initial: A

State: FL ZIP: 33837

Last Name: Smith

Country: USA

Age at time of Accident/Incident: 33 Date of Birth: mm/dd/yyyy

Certificate Number:

Degree of Injury

☐ None ☒ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☒ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available	Used
☐ None	☐ None
☐ Lap only	☐ Lap only
☐ 3-point	☐ 3-point
☒ 4-point	☐ 4-point
☐ 5-point	☐ 5-point
☐ Unknown	☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☒ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None	☐ Flight Instructor	☒ Commercial	☐ US Military
☒ Private	☐ Recreational	☒ Airline Transport	☐ Foreign
☐ Student	☐ Sport	☐ Flight Engineer	

Principal Occupation

☒ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☒ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☒ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

03/09/2018
mm/dd/yyyy

Medical Certificate Limitations

NONE

Medical Certificate Special Issuance

N/A

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

08/31/2018
mm/dd/yyyy

Flight Review Aircraft

Make: Dasult Falcon

Model: DA-20

Airplane Rating(s)
(Check all that apply)

☐ None
☒ Single-Engine Land
☐ Single-Engine Sea
☒ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)
(Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)
(Check all that apply)

☐ None
☒ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)
(Check all that apply)

☐ None	☐ Instrument Airplane
☐ Airplane Single-Engine	☐ Instrument Helicopter
☐ Airplane Multi-Engine	☐ Helicopter
☐ Gyroplane	☐ Glider
☐ Powered Lift	☐ Sport

Type Ratings

LR-Jet, DA-20, CL601

Student Endorsements (Include dates)**Flight Time** (Enter appropriate number of hours in each box)

	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	3,806	201	1,311	2,496						
Pilot in Command (PIC)	2,687									
Time as Instructor										
This Make/Model										
Last 90 Days	64									
Last 30 Days	72									
Last 24 Hours	6									

FLIGHT ITINERARY INFORMATION					
Last Departure Point Airport ID: <u>KYIP</u> City: <u>Ypsilanti</u> State: <u>MI</u> Country: <u>USA</u>		Time of Departure Time: <u>0513</u> Time Zone: <u>EDT</u>		Destination Airport ID: <u>KOSC</u> City: <u>Oscoda</u> State: <u>MI</u> Country: <u>USA</u>	
				Type Flight Plan Filed ☐ None ☐ VFR/IFR ☐ Company VFR ☒ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☒ Yes ☐ No ☐ Unknown	
Type of ATC Clearance/Service (Check all that apply) ☐ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise ☐ VFR ☒ IFR ☐ VFR On Top ☐ Traffic Advisory ☐ Unknown / NA					
Airspace where the accident/incident occurred (Check all that apply) ☐ Class A ☐ Class G ☐ Military Operations Area (MOA) ☐ Special ☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area ☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown ☐ Class D ☐ Prohibited Area ☐ TRSA ☒ Class E ☐ Restricted Area ☐ FAR 93					Altitude of In-Flight Occurrence: _____ ft msl
WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE					
Source of Pilot Weather Information (Check all that apply) ☐ National Weather Service ☐ Company ☐ Flight Service Station ☐ Military ☐ TV/Radio ☐ Internet ☐ Automated Report ☐ None ☐ Commercial Weather Service (DUATS) ☐ Unknown ☐ On-Board Weather			Weather Observation Facility Facility ID: _____ Observation Time: _____ Time Zone: _____ Distance from Accident Site: _____ nm Direction from Accident Site: _____ degrees true		
Basic Conditions ☐ VMC ☒ IMC ☐ Unknown		Light Condition ☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown ☐ Day ☒ Night ☐ Bright Night			
Sky/Lowest Cloud Condition ☐ Clear ☐ Thin Broken ☐ Few ☐ Thin Overcast ☐ Partial Obscuration ☐ Unknown ☐ Scattered		Ceiling ☐ None (Clear) ☐ Obscured ☐ Broken ☐ Indefinite ☒ Overcast ☐ Unknown		Temperature: <u>18</u> (C) or _____ (F) Dew Point: <u>18</u> (C) or _____ (F) Altimeter Setting: <u>29.91</u> in. Hg or _____ MB	
Lowest Cloud Condition Height _____ ft agl		Ceiling Height <u>400</u> ft agl			
Wind Direction ☐ Variable -or- Direction: <u>180</u> degrees true	Wind Speed ☐ Calm ☐ Light and Variable -or- Speed: <u>7</u> kts	Wind Gusts ☒ Not Gusting -or- Speed: _____ kts	Visibility <u>5</u> miles RVR: _____ feet RVV: _____ miles Density Altitude: _____ ft		
Intensity of Precipitation ☒ Light ☐ Moderate ☐ Heavy ☐ N/A ☐ Unknown	Type of Precipitation (Check all that apply) ☐ None ☐ Drizzle ☐ Freezing Rain ☒ Rain ☐ Ice Pellets ☐ Snow Shower ☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower ☐ Hail ☐ Snow Grains ☐ Freezing Drizzle ☐ Rain Showers ☐ Ice Crystals		Restriction to Visibility (Check all that apply) ☐ None ☐ Fog ☐ Blowing Dust ☐ Ground Fog ☐ Blowing Sand ☐ Haze ☐ Blowing Snow ☐ Ice Fog ☐ Blowing Spray ☐ Smoke ☐ Dust ☒ Unknown		
Icing Forecast Amount ☐ None ☐ Trace ☐ Light ☐ Moderate ☐ Severe ☐ Unknown Type ☐ N/A ☐ Rime ☐ Clear ☐ Mixed ☒ Unknown		Icing Actual Amount ☐ None ☐ Trace ☐ Light ☐ Moderate ☐ Severe ☐ Unknown Type ☐ N/A ☐ Rime ☐ Clear ☐ Mixed ☒ Unknown		Turbulence Type (Check all that apply) ☒ None ☐ Clear Air ☐ Terrain-Induced ☐ Convective Turbulence Severity ☐ Light ☐ Moderate ☐ Severe ☐ Extreme	
NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident: FDC NOTAMS OSC- rwy 24 approach lights out of service OSC- 06/24 changes 07/25 OSC- obstacle tower light out of service OSC ILS NAV 24 out of service					

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☐ Substantial
☐ Minor ☒ Destroyed
 ☐ Unknown

Aircraft Fire

- ☐ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☒ On-Ground ☐ Unknown

Aircraft Explosion

- ☐ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☒ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Aircraft crashed in heavily wooded area 5.8 miles south west of Oscoda Airport. Aircraft impacted ground resulting with intense fire destroying majority of aircraft.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

ALL TIME APPROXIMATE

Aircraft departed KYIP at 0910z with 1-pilot on board en route to KOSC. Aircraft operated on a IFR flight plan.

At 1020 z Company personnel telephoned Kalitta Charters dispatch to inquire aircraft location.

1025z- Dispatch attempted to cal PIC on cell phone-no answer

1030z -tried cell phone again-no answer

1040z- Company personnel had driven around the airport, physically looking for the aircraft

1050z- Dispatch called MSP center who reported PIC did not close the flight plan

1115z- Dispatch spoke with MSP center who indicated they were going to commence search

1155z- Company personnel began search off airport property

1430z- Township Police located aircraft wreckage on dense forested federal land approximately 5 mile Southwest of KOSC airport

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No
(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Total Time/Cycles
On Part____ Hours
____ CyclesTime Since This Part
Inspected/Overhauled

____ Hours

FUEL & SERVICES INFORMATIONFuel on Board at Last Takeoff
(Convert from pounds, as necessary)

450 Gallons

Fuel Type

☐ 80/87 ☐ 115/145 ☐ Jet B ☐ Other, specify _____
☐ 100 Low Lead ☒ Jet A ☐ JP8
☐ 100/130 ☐ Jet A-1 ☐ Automotive

Other Services, if Any, Prior to Departure

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☐ Yes ☒ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed ☐ Minor
☐ Substantial ☐ None

Registered Owner of Other Aircraft

Name: _____
City: _____
State: _____ ZIP: _____
Country: _____

Pilot of Other Aircraft

Name: _____
City: _____
State: _____ ZIP: _____
Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE**Date of this Report**10/01/2018*mm/dd/yyyy***Name of Pilot/Operator:** _____**Signature:** _____-- or -- ☐ Check here to electronically sign this document**If a Person Other than Pilot/Operator is Filing Report****Name:** Heath Nicholl**Title:** Director of Safety Kalitta Charters**Signature:** _____-- or -- ☐ Check here to electronically sign this document**FOR NTSB USE ONLY****NTSB Accident/Incident No.**
CEN18FA387**Reviewed by NTSB Regional Office**
DENVER, CO**Name of Investigator**
ARNOLD W. SCOTT**Date Report Received**
10/01/2018