



Photo 1 – Tree crown and height of trees struck.



Photo 2 – Swath cut through trees.



Photo 3 – Propeller strike.



Photo 4 – Severed tree branch.



Photo 5 – Propeller A.



Photo 6 – Propeller B.



Photo 7 – Wing and cockpit area_Redacted.



Photo 8 – Opposite end of wing and cockpit area.



Photo 9 – First engine.



Photo 10 – Remains of second engine.



Photo 11 – Part of the left wing.



Photo 12 – Part of the right wing_Redacted.