



RECORD OF EXAMINATION

Mitchell Gallo
Aviation Accident Investigator
Central Region

NTSB Accident Number: CEN18LA017

Location: Port Mansfield, Texas

Participants: Carl Newton, Federal Aviation Administration, San Antonio FSDO

Narrative:

Post-accident examination of the nose landing gear revealed a fractured trunnion casting. No mechanical anomalies that would have precluded normal operation were noted.

Mitchell Gallo
Air Safety Investigator