



Photo 1 – Right, rear quartering view of the wreckage near a localizer antenna array.



Photo 2 - Left, front quartering view of the wreckage.



Photo 3 - View of ground scars to the east of the wreckage.



Photo 4 - View of the interior of the airplane looking forward from the aft entry door.



Photo 5 - View of the cockpit.



Photo 6 - View of the fuel control panel.



Photo 7 - View of gages on the right side of the cockpit.




Photo 8 - View inside the opened right nacelle fuel tank.




Photo 9 - View inside the opened left nacelle fuel tank.



Photo 10 - View of the opened left fuel filter bowl containing a liquid.



Photo 11 - View of the disassembled right engine driven fuel pump.



Photo 12 - View of the opened right fuel filter bowl containing a liquid.



Photo 13 - View of the disassembled left engine driven fuel pump.



Photo 14 - View of the left side of the recovered wreckage.



Photo 15 - View of the front of the recovered wreckage.



Photo 16 - View of the lower instrument panel on the right side of the pedestal.



Photo 17 - View of the upper portion of the pedestal.



Photo 18 - View of the lower portion of the pedestal.



Photo 19 - View of the left nacelle fuel tank's pump with a separated electric wire.



Photo 20 - Close-up view of bearings from an engine driven fuel pump.