



**Photo 1 – Main wreckage, right side**



**Photo 2 – Empennage**




**Photo 3 – Engine accessory area**




**Photo 4 – Oil filter and oil cooler**




**Photo 5 – Oil filter and safety wire**



**Photo 6 – SkyVector flight path from 4XA2 to 8T6**



**Photo 7 – Accident flight path**



**Photo 8 – Accident flight path and accident site**



**Photo 9 – Accident flight path and accident site next to 2XS7**